

Tabla de la función de error

4.7 Industrial Applications of Diffusion Processes

Table 4.5 Table of the Error Function

z	$\text{erf } z$	z	$\text{erf } z$	z	$\text{erf } z$	z	$\text{erf } z$
0	0	0.40	0.4284	0.85	0.7707	1.6	0.9763
0.025	0.0282	0.45	0.4755	0.90	0.7970	1.7	0.9838
0.05	0.0564	0.50	0.5205	0.95	0.8209	1.8	0.9891
0.10	0.1125	0.55	0.5633	1.0	0.8427	1.9	0.9928
0.15	0.1680	0.60	0.6039	1.1	0.8802	2.0	0.9953
0.20	0.2227	0.65	0.6420	1.2	0.9103	2.2	0.9981
0.25	0.2763	0.70	0.6778	1.3	0.9340	2.4	0.9993
0.30	0.3286	0.75	0.7112	1.4	0.9523	2.6	0.9998
0.35	0.3794	0.80	0.7421	1.5	0.9661	2.8	0.9999

Source: R. A. Flinn and P. K. Trojan, "Engineering Materials and Their Applications." 2d ed., Houghton Mifflin, 1981, p. 137.